## http://www.kuonline.in

Total Pages: 3

10

[P.T.O.

Roll No.

	O1 11111111111111111						
	BT-8	3/D-17	38018				
TRANSDUCER AND THEIR APPLICATIONS  Paper: ECE-430E							
Time: Three Hours]		[Maximum]	Marks: 100				
<b>Note:</b> Attempt <i>five</i> questions in all, selecting atleast <i>one</i> question from each section.							
SECTION-I							
1. (a	) What is the difference	between accuracy and	d precision ?				
(b	) What is the 5% settlir first-order instrument	-	-				
(c	) Explain Hall effect is application of Hall ef	-	ve different 10				
2. (a	A capacitive transductive area 750 mm <sup>2</sup> separate pressure of 900 kN/m produces a deflection 370 pF when no pressure 900 kN/m <sup>2</sup> .	ated by a distance of a when applied to top of 0.6 mm. The casture is applied to the	3.5 mm. A p diaphragm pacitance is diaphragm.				
(b	) Draw and explain w	orking of LVDT. V	What causes				

***	00	DT/	~~	
SŁ	U	ш	יוכ	II-II

- 3. (a) Explain in detail about the functioning of different force summing devices.
  - (b) Find seeback voltage for a thermocouple with proportionality constant of 40 μV/°C if the junction temperatures are 40°C and 80°C.
- 4. (a) What is the need of lead wire compensation? How is it to be done in RTD? What is self heating effect in RTD?
  - (b) For a certain thermistor  $\beta = 3140$  K and at 27°C is known to be 1050  $\Omega$ . The thermistor is used for temperature measurement and the resistance measured is as 2330  $\Omega$ . Find the measured temperature.

## SECTION-III

- (a) Explain with a sketch the principle of operation of a variable reluctance accelerometer.
  - (b) Explain in detail the working of toothed rotor tachometer generator. http://www.kuonline.in 10
- through an amplifier whose amplification factor is 250.

  An output of 2 mV appears across the terminals of LVDT when the core moves through a distance of 0.5 mm. Calculate the sensitivity of LVDT.
  - (b) Explain different non-electrical methods for measurement of temperature.

residual voltage to occur?

38018/900/KD/1574

## http://www.kuonline.in

## SECTION-IV

- (a) Define torque. Explain in detail absorption type dynamometers.
  - (b) Explain different methods used to measure velocity.

10

- 8. Explain the following:
  - (a) Load Cells.
  - (b) Photoelectric Tachometer.
  - (c) Piezoelectric Transducer.
  - (d) Metallic Resistance Thermometers. (5×4=20)

38018/900/KD/1574